



IT認證考試題庫 專業平臺

考證寶提供最新考古題與模擬試題
協助您高效通過認證考試

www.kaozhengpro.com

Exam : **HP2-T23**

Title : Supporting Industry
Standard Server Solutions

Version : DEMO

1.You cannot get to the network from any of the server blades in a c7000 enclosure with 10GbE Pass-Thru modules.

What should you verify first for proper connectivity to the network?

- A. Correct SFPs are installed
- B. External switch supports at least Gigabit speed
- C. Interconnect link between the Pass-Thru modules
- D. External switch set to half duplex

Answer: C

2.Which statements are correct about HP Systems Insight Manager (HP SIM) 7.0 Agentless Management? (Select two.)

- A. HP SIM communicates with the CPU and collects essential data for the operating system.
- B. Agentless Managements provided by the CPU.
- C. HP SIM communicates with the iLO Management Engine to collect hardware data.
- D. The Agentless Management Service runs on the host to provide software information directly to the iLO Management Engine.

Answer: C,D

Reference:<http://h20000.www2.hp.com/bc/docs/support/SupportManual/c03306157/c03306157.pdf>
(page 2)

3.Which statements are correct about HP Systems Insight Manager (HP SIM) 7.0 Agentless Management? (Select two.)

- A. HP SIM communicates with the CPU and collects essential data for the operating system.
- B. Agentless Management is provided by the CPU.
- C. HP SIM communicates with the iLO Management Engine to collect hardware data.
- D. The Agentless Management Service runs on the host to provide software information directly to the iLO Management Engine.

Answer: C,D

4.A customer lost the password information for the Onboard Administrator of a C7000 enclosure and asks you to restore administrator access.

How should you do this?

- A. Connect to the serial port of the Onboard Administrator and press the reset button to restore the default password.
- B. Use HP SUM in Recovery mode.
- C. Run the Onboard Administrator Recover option from one of the server blades in the enclosure.
- D. Run Remote Insight Board Command Language (RIBCL) from the Insight Display.

Answer: A

Reference:http://h20566.www2.hp.com/portal/site/hpsc/template.PAGE/public/kb/docDisplay/?sp4t_s.oid=1844065&spf_p.tpst=kbDocDisplay&spf_p.prp_kbDocDisplay=wsrpnavigationalState%3DdocId%253Demr_na-c0111586616%257CdocLocale%253D%257CcalledBy%253D&javax.portlet.begCacheTok=com.vignette.cac_hetoken&javax.portlet.endCacheTok=com.vignette.cachetoken

5.Microsoft Windows BitLocker Encryption feature uses a TPM microcontroller chip to store certificates

and encryption keys on a DL380 G7.

Which action must a field engineer perform before upgrading server firmware and installing an additional storage controller?

- A.Create new certificates and encryption keys.
- B.Disable BitLocker.
- C.Delete certificates and encryption keys.
- D.Disable TPM.

Answer: B

6.What is the name of the HP agent that enables a customer to manage HP software that is stored in a user-defined repository?

- A.Web-Based Enterprise Management (WBEM)
- B.Version Control Repository Manager (VCRM)
- C.Version Control Agent
- D.Data Collection Reports

Answer: B

Reference:http://h20565.www2.hp.com/portal/site/hpsc/template.BINARYPORTLET/public/kb/docDisplay/resource.process/?spf_p.tpst=kbDocDisplay_ws_BI&spf_p.rid_kbDocDisplay=docDisplayResURL&javax.portlet.begCacheTok=com.vignette.cachetoken&spf_p.rst_kbDocDisplay=wsrresourceState%3DdocId%253Demr_na-c031689542%257CdocLocale%253Den_US&javax.portlet.endCacheTok=com.vignette.cachetoken(page 20, see HP version control repository manager)

7.What happens if you lose or misplace a Trusted Platform Module (TPM) key?

- A.The system requests the Administrator password.
- B.The system enters diagnostic mode.
- C.The system will not boot.
- D.Data loss might occur.

Answer: D

8.An engineer is installing an HP R7000 UPS and an Extended Runtime Module (ERM) in an existing HP 10642 G2 rack.This rack contains 10 ProLiant DL380e Gen8 servers mounted from 1U upward.

How should the engineer perform this installation?

- A.Mount the R7000 UPS at 10U in the 10642 G2 rack with the ERM on top of the R7000 UPS.
- B.Remove the lowest ProLiant DL380e Gen8 servers and mount the R7000 and the ERM at the lowest position in the rack.Mount the removed ProLiant DL380e Gen8 servers at a higher position in the 10642 G2 rack.
- C.Mount the R7000 at the highest position possible in the 10642 G2 rack with the ERM just below the UPS.
- D.Remove the two lowest mounted ProLiant DL380e Gen8 servers and mount the R7000 at the bottom of the 10642 G2 rack.Mount the two removed ProLiant DL380e Gen8 servers at the top of the 10642 G2 rack.Mount the ERM above the remaining original mounted ProLiant DL380e Gen8 servers.

Answer: B

9.Which RAID level is known as Advance Data Guarding (ADG)?

- A.RAID 1
- B.RAID 5
- C.RAID 6
- D.RAID 10

Answer: C

Reference:<http://h50146.www5.hp.com/products/storage/whitepaper/pdfs/c00386950.pdf>

10.Which HP utility can patch a ProLiant server with a release set made up of drivers, firmware, and software that have been tested together?

- A.HP Smart Update Firmware DVD
- B.HP Version Control Update (VCU)
- C.Integrated Lights Out (iLO)
- D.Service Pack for ProLiant (SPP)

Answer: D